



Kongelysvej 6B, DK-2820 Gentofte

Tlf. +45 7027 6780 – Fax +45 3555 7149 – email ijcu@ijcu.dk



Kongelysvej 6B, DK-2820 Gentofte

Tlf. +45 7027 6780 – Fax +45 3555 7149 – email ijcu@ijcu.dk




Emergency pull fitting



Kongelysvej 6B, DK-2820 Gentofte

Tlf. +45 7027 6780 – Fax +45 3555 7149 – email ijcu@ijcu.dk



Locking handle bracket pushbutton, and operation manual situation marking decal



Push it to open lock handle bracket



Kongelysvej 6B, DK-2820 Gentofe

Tlf. +45 7027 6780 – Fax +45 3555 7149 – email ijcu@ijcu.dk



Open lock handle bracket



Locking handle bracket with opening



Kongelysvej 6B, DK-2820 Gentofte

Tlf. +45 7027 6780 – Fax +45 3555 7149 – email ijcu@ijcu.dk



Emergency pull fitting



Emergency pull fitting



Kongelysvej 6B, DK-2820 Gentofe

Tlf. +45 7027 6780 – Fax +45 3555 7149 – email ijcu@ijcu.dk



Emergency pull fitting, pull emergency pull tape to open lock handle bracket for right door leaf



And then, Push away right door leaf from inside



Kongelysvej 6B, DK-2820 Gentofe

Tlf. +45 7027 6780 – Fax +45 3555 7149 – email ijcu@ijcu.dk



Locking handle bracket with unlocked



Locking handle bracket with unlocked



Kongelysvej 6B, DK-2820 Gentofte

Tlf. +45 7027 6780 – Fax +45 3555 7149 – email ijcu@ijcu.dk



Locking handle bracket with locking by key



Locking handle bracket with locked by key that right door leaf can not be opened.



Kongelysvej 6B, DK-2820 Gentofe

Tlf. +45 7027 6780 – Fax +45 3555 7149 – email ijcu@ijcu.dk